


## Factory Certificate of Calibration

Product Name	LOGIC BASIC	Name of Inspection Standard	lg2110
Model No.		Unit	inch
Serial No.		Scale Interval	0.0001 inch
		Measuring Range	1 inch
Certificate No.		Reference Point	0 inch
NIST No. 821/268795-03		End Point	1 inch


N.I.S.T. No. 821/268795-03

Inspection Item Name	Result	Permissible Value	Judgment GO N/A GO	
Indication Error	0.0000611 inch	0.0002 inch		
Hysteresis	***************************************	0.0001 inch		
Repeatability	0.000002 inch	0.0001 inch		
Max. Measuring Force			N/A	

Inspection Item Name	Judgment
Inspection of Function and Appearance	GO



Indication Error is the sum of accuracy and quantizing error.



Repeatability is taken at three positions, with five readings at each position.

Signature			